## AMENDMENTS TO THE SPECIFICATION

Please replace Paragraph [0005] with the following paragraph rewritten in amendment format:

If using two slots having 4G upstream bandwidth substitutes as one slot of the original four slots with 8G upstream bandwidth, two 400M-Ethernet process boards <u>each support a plurality of 100M Ethernets</u> can be plugged in the switch. Nevertheless, there are only three slots are available for service processing board with 8G bandwidth. If a service processing board with 8G bandwidth is plugged in the slot with upstream bandwidth 4G, it will cause 50% service flow to be blocked. In some cases, this design is forbidden

Serial No. 10/613.162